HISTORIC AMERICAN LANDSCAPES SURVEY

INDEX TO PHOTOGRAPHS

SKYLINE PARK 1500-1800 Arapahoe Street Denver Denver County Colorado

HALS No. CO-1

INDEX TO BLACK AND WHITE PHOTOGRAPHS

- Gifford Ewing, Photographer, May 2003 CO-01-1 Block 1. Photograph depicts general view of the pedestrian entrance from the south corner towards the fountain on Block 1. Block 1. Photograph depicts general view of the pedestrian entrance from CO-01-2 the southwest corner towards the fountain on Block 1. CO-01-3 Block 1. Photograph shows general view of the western side from the southern portion towards the midsection of Block 1. CO-01-4 Block 1. Photograph shows the general view of the southern side and the middle section of Block 1, southern side of the fountain and includes the May D & F Tower. Block 1. Photograph shows the general view of the southern side and CO-01-5 middle section of Block 1, southern side of the fountain and includes the May D & F Tower. Block 1. Photograph shows the southern view of the fountain on Block
- CO-01-6 one from the pedestrian entrance.
- Block 1. Photograph shows the southern view of the fountain on block CO-01-7 one from the pedestrian entrance.
- CO-01-8 Block 1. Photograph depicts the southern pedestrian entrances (southern portion of block 1) from within the park towards street.
- CO-01-9 Block 1. Photograph depicts close up view (eastern side) of working fountain on Block 1 and reveals how the water flowed through the fountain.

CO-01-10 Block 1. Photograph depicts close up view (eastern side) of working fountain on Block 1 and reveals how the water flowed through the fountain. Block 1. Photograph shows general view of the southern portion of the CO-01-11 fountain and the surrounding vicinity. Block 1. Photograph shows general view of the northern portion of the CO-01-12 fountain and the surrounding vicinity. CO-01-13 Block 1. Photograph shows general view of the northern base of the fountain and the surrounding vicinity. Block 1. Photograph depicts a close up view of the eastern side of the CO-01-14 fountain on block 1. Block 1. Photograph represents general view taken from the base of CO-01-15 fountain towards the May D&F Tower. Photograph includes vertical light structure with drinking fountain, berms, trees and shrubs, and benches that are placed within northern half of Block 1. CO-01-16 Block 1. Photograph represents general view taken from the base of fountain towards the May D&F Tower. Photograph includes vertical structure with drinking fountain, berms, trees and shrubs, and benches that are placed within northern half of Block 1. Photograph includes full façade of May D & F Tower. CO-01-17 Block 1. Photograph depicts close up view of northern side of the fountain on Block 1. CO-01-18 Block 1. Photograph portrays general view of designated seating area at mid point of block 1 and illustrates poor maintenance of vegetation within the park. CO-01-19 Block 1. The photograph shows a general view of the midsection of Block 1 in the southeast direction. It reveals berms, benches and wall seats within the park

Block 1. Photograph represents general view taken from the middle of

block 1 towards the southern boundary of park. Photograph portrays berms and shrubs, building façade on western boundary of the park and

water feature within block 1.

CO-01-20

- CO-01-21 Block 1. Photograph illustrates the public gathering space on block 1 and a building that borders the northwestern side of the block.
- CO-01-22 Block 1. Photograph shot from within public gathering space towards the northwest entrance of Block 1 and depicts stair entrance to the block. The base of the May D & F Tower is in the background.
- CO-01-23 Block 1. Photograph shot from the northern pedestrian entrance of Block 1 and depicts berms, seat walls, trees and public gathering space.
- CO-01-24 Block 1. Photograph represents general view taken from the midsection of Block 1 towards the southern boundary of the park. Photograph depicts designated seating area, berms and shrubs, vertical light features and a fountain. In addition, photograph shows a partially damaged concrete structure.
- CO-01-25 Block 1. Photograph shot from the northwest pedestrian entrance of Block 1 and it depicts a public gathering space and a fountain.
- CO-01-26 Block 1. Aerial Photograph taken from the top of the May D & F Tower and depicts the entire Block 1. Photograph shows the two public gathering spaces, a mid-section designated seating area and the fountain. In addition, the photograph shows an exit from underground public parking off eastern side along the street front.
- CO-01-27 Block 1. Aerial view taken looking northwest from Independence Tower Photograph depicts fountain and designated seating area within Block 1 and shows the design and spatial sequence of the block.
- CO-01-28 Blocks 1 and 2. Aerial view to the northwest, taken from Independence Tower, depicts the May D & F Tower and the eastern portion of Block 1. Photograph includes context of surrounding streets and buildings.
- CO-01-29 Block 1 and 2. Aerial view taken from Independence Tower and depicts the entire Block 1 and southern base of Block 2. Photograph includes close-up view of May D & F Tower and the surrounding setting.
- CO-01-30 Block 2. Aerial Photograph taken from the top of the May D & F Tower and depicts the entire Block 2 Photograph shows the two public gathering spaces on the northern and southern sides of block, a midsection and the fountain. In addition, photograph shows maintenance structure next to street.

CO-01-31 Block 2. Photograph represents general view taken from the northeast corner of the May D & F Tower. Photograph shows the main public gathering space within Skyline Park. Block 2. Photograph represents general view taken from the north/west CO-01-32 region of the May D & F Tower. Photograph shows the main public gathering space for Skyline Park and depicts a light feature and an "Information" sign. CO-01-33 Block 2. Photograph shows general view from the western boundary of the park towards street and parallel to the May D & F Tower and main public gathering space. Block 2. Photograph shows general view of the main public gathering CO-01-34 space and surrounding building facades. Block 2. Photograph shows general view the southwest corner of the main CO-01-35 public gathering space and surrounding building facades. Block 2. Photograph shows general view from within the main public CO-01-36 gathering space towards the northern boundary of Block 2. Photograph depicts a vertical light structure, stair walls, trees and benches. CO-01-37 Block 2. Photograph shows general view from within the main public gathering space towards the northern boundary of Block 2. Photograph depicts vertical structures, stair walls, trees and benches. CO-01-38 Block 2. Photograph shows general view of the main public gathering space from the western boundary towards street. Photograph depicts standard use of bricks within the gathering spaces. CO-01-39 Block 2. Photograph shows general view of the main public gathering space from the western boundary towards Arapahoe Street. Photograph depicts standard use brick and concrete within the park. CO-01-40 Block 2. Photograph depicts general view from the mid of Block 2 towards the base of the May D & F Tower. CO-01-41 Block 2. Photograph shows general view from mid-block across the main public gathering space towards the southwestern corner of Block 2.

Photograph portrays a vertical light structure and building facades located

on the western edge of the park.

CO-01-42 Block 2. Aerial view taken from Independence Tower and depicts view of main gathering space directly north of the May D & F Tower. Block 2. Photograph shows general view from midsection towards the CO-01-43 northern boundary of Block 2. Photograph depicts vertical structures, berms, trees and benches. Block 2. Photograph shows close up, western view of the fountain on CO-01-44 Block 2. In addition, photograph includes two light features that are situated along the western side of the fountain. CO-01-45 Block 2. Photograph depicts close up of stair wall, which is located opposite of the fountain on block 2. Photograph reveals the porous quality of the concrete used within the park. CO-01-46 Block 2. Photograph shows close-up, southern view of the fountain on Block 2. CO-01-47 Block 2. Photograph shows general view across from fountain towards northern side of Block 2 and includes northern corner of fountain, and the two pedestrian entrances to Block 2. CO-01-48 Block 2. Photograph shows general view opposite the fountain looking towards the middle section of Block 2 and depicts close up view of a stair wall. Block 2. Photograph taken from western side of Block 2 and reveals CO-01-49 general view of the northern portion of Block 2 and includes a small portion of the fountain shown in lower right of photograph CO-01-50 Block 2. Photograph shows general view from the northwestern corner of Block 2 and includes a close up view of the fountain. CO-01-51 Block 2. Photograph shows general view from the northern side towards midsection of block 2 and includes northern view of the fountain. CO-01-52 Block 2. Photograph depicts general view of Block 2 from northern pedestrian entrance to Block 2 towards the May D & F Tower. CO-01-53 Block 2. Photograph depicts general view of Block 2, fountain and the May D & F Tower from the northern pedestrian entrance. In addition,

photograph includes a Skyline Park entrance sign.

Block 2. Photograph shows the view from pedestrian entrance in towards CO-01-54 fountain and includes close up view of the entrance light feature. CO-01-55 Block 2. Aerial view taken from Independence Tower and depicts the north half of Block 2 with the fountain. CO-01-56 Blocks 2 and 3. Aerial view taken from the top of Independence Tower (southern side of Arapahoe Street) depicts the north half of Block 2 with the fountain. Block 3. General view of pedestrian entrance displaying a light feature CO-01-57 near the eastern entrance of park. CO-01-58 Block 3. Photograph shows general view of the walkway that aligns with the western building facades. Photograph is taken from the pedestrian entrance and shows benches and light features. CO-01-59 Block 3. General view of the northwest pedestrian entrance of Block 3 demonstrating the change in grading throughout the park and the change in building materials (brick and concrete). Photograph exhibits stair walls, berms and trees. CO-01-60 Block 3. Northern view observed from within central portion of Block 3. Photograph exhibits a vertical structure, stair walls, berms and trees. Block 3. Southeastern view observed from within central portion of Block CO-01-61 3. Photograph reveals the change in grade along the central path, light fixtures built within the vertical walls at ground level along ramps and entrances. CO-01-62 Block 3. Southeastern view observed from within central portion of Block 3. Photograph exhibits stair walls, berms and trees. Block 3. Southeastern view towards the May D & F Tower observed from CO-01-63 within central portion of Block 3. Photograph exhibits stair walls, berms and trees. Block 3. This photograph depicts the northern view of Block 2 towards CO-01-64 the May D & F Tower from the main path along the western facades. CO-01-65 Block 3. Southern view observed from within central portion of Block 3.

Photograph exhibits stair walls, berms and trees. This photograph illustrates the use of brick and concrete treatment designs for the

walkways throughout the park.

CO-01-66 Block 3. Central view of Block 3 observed from the west to the east. This photograph reveals the alignment of trees within the central path of the park. In addition, this photograph exposes broken bricks aligning tree beds. CO-01-67 Block 3. View of central path aligned with stair wall and berm towards the back or rear side of fountain (right side of photograph). CO-01-68 Block 3. General interior view shot towards the northwest pedestrian entrance of Block 3 revealing fountain, stair walls, two vertical light structures and berms. CO-01-69 Block 3. General interior view exposes berms, stair walls, trees and a vertical light fixture. CO-01-70 Block 3. This photograph is a general view shot from within Skyline Park towards the northwest entrance of Block 3 and it shows two vertical light structures, water fountain, berms and stair walls. CO-01-71 Block 3. General view exposes the fountain, berms and stair walls. Photograph reveals the designer's use of building materials (bricks and concrete). CO-01-72 Block 3. This photograph is a general view of pedestrian entrance into Skyline Park at the northwest entrance next to the western building facades showing light features and the May D & F Tower. Two vertical light structures and fountain are shown in central portion of photograph. CO-01-73 Block 3. This photograph is a general view of pedestrian entrance into Skyline Park from the northwest entrance of Block 3. It encompasses a fountain (left side of photograph), berms and stair walls. Two vertical light features are situated within the central portion of the photograph. CO-01-74 Block 3. Aerial view taken from top of Independence Tower and depicts southern half of Block 3 and depicts the dense number of trees (a characteristic design element) on Block 3.


Block 3. Aerial view taken from the top of Independence Tower

(southern side of Arapahoe Street) and shows entire Block 3 within its


CO-01-75

surrounding setting.

SKYLINE PARK HALS CO-1 INDEX TO PHOTOGRAPHS (Page 8)



NOTE: Photographs no. 27, 28, 29, and 42 are aerial photos and not located on map.



NOTE: Photographs no. 55, 56, 74 and 75 are aerial photos and not located on map.

